

Order-No.: DD+DIS272.99E

November 1999



1 Piece QG4BG MA1

ADC Compact

Type 5145

ADC Solo

Type 5155


Please file this document in section 13 of your Technical Documentation

Jumper Configuration of (GS310) VME-Harddisk ADCC/ADCS

Before installing a new harddisk CM+7.0486.1260.0 after a harddisk crash, check if the jumper configuration of the new HDD is correct.

Due to production reasons the jumper configuration of the harddisks may vary.

The correct jumper configuration is shown in the figure below.



correct
jumper configuration